Xpass

Firmware Revision Notes

Version 1.2

Revision Notes

Firmware Version 1.2   **Build Number V1.2_110305**   2011-03-05

- Support Interlock Zone.

  - It is possible to configure two doors as an interlock zone.

- Support Mifare Card.

  - Read data saved in each sectors of Mifare Card.

  - Write data to each sectors of Mifare Card.

- Support Mifare Plus Card.

  - Support CSN reading.

  - Read data saved in each sectors of Mifare Plus Card.

  - Write data to each sectors of Mifare Plus Card.

- Support Mifare Desfire and Ultralight card.

  - Support CSN reading only.

- In case of succeed in network setting, BEEP sounds and green LED turns on.

- The following bugs are fixed.

  - Using HID card, there was no validation about card data length.

  - Using Unlock Time, forced open event does not occur.

  - Using Command card to enroll a new user, previously enrolled user card cannot be used any more.

  - On March 2 of 2011, the date of some devices might have been reset to March 1 of 2011, one day earlier than the actual date.

  - On January 1 of 2012, the date of some device may be set to January 1 of 2014.

Firmware Version 1.1   **Build Number V1.1_101110**   2010-11-10

- The following bugs are fixed.

■ Set time for device, it does invalid value set.

Firmware Version 1.1   **Build Number V1.1_100427**   2010-04-27

- Support a new RF card type EM/HID.

- Enhanced the performance of booting than V1.0

Firmware Version 1.0   **Build Number V1.0_091223**   2009-12-23

- Created.