






### 3. PZ Models



Step 1.  
Install cable to bracket




Step 2.  
Connect cable to camera



5

EN


### ■ Cable Connection



Cable includes  
power, RS-485, video  
out.



RS-485 interface is two cable  
Purple color is 485 A/+  
Grey color is 485 B/-



Video out interface



Power interface,  
Need to connect +12V DC  
Inside is (+),  
Outside is (-).

EN

6